

Алматы (7273)495-231
 Ангарск (3955)60-70-56
 Архангельск (8182)63-90-72
 Астрахань (8512)99-46-04
 Барнаул (3852)73-04-60
 Белгород (4722)40-23-64
 Благовещенск (4162)22-76-07
 Брянск (4832)59-03-52
 Владивосток (423)249-28-31
 Владикавказ (8672)28-90-48
 Владимир (4922) 49-43-18
 Волгоград (844)278-03-48
 Вологда (8172)26-41-59
 Воронеж (473)204-51-73
 Екатеринбург (343)384-55-89

Ижевск (3412)26-03-58
 Иваново (4932)77-34-06
 Иркутск (395)279-98-46
 Казань (843)206-01-48
 Калининград (4012)72-03-81
 Калуга (4842)92-23-67
 Кемерово (3842)65-04-62
 Киров (8332)68-02-04
 Коломна (4966)23-41-49
 Кострома (4942)77-07-48
 Краснодар (861)203-40-90
 Красноярск (391)204-63-61
 Курск (4712)77-13-04
 Курган (3522)50-90-47
 Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
 Москва (495)268-04-70
 Мурманск (8152)59-64-93
 Набережные Челны (8552)20-53-41
 Нижний Новгород (831)429-08-12
 Новокузнецк (3843)20-46-81
 Ноябрьск (3496)41-32-12
 Новосибирск (383)227-86-73
 Омск (3812)21-46-40
 Орел (4862)44-53-42
 Оренбург (3532)37-68-04
 Пенза (8412)22-31-16
 Петрозаводск (8142)55-98-37
 Псков (8112)59-10-37
 Пермь (342)205-81-47

Россия (495)268-04-70

Ростов-на-Дону (863)308-18-15
 Рязань (4912)46-61-64
 Самара (846)206-03-16
 Саранск (8342)22-96-24
 Санкт-Петербург (812)309-46-40
 Саратов (845)249-38-78
 Севастополь (8692)22-31-93
 Симферополь (3652)67-13-56
 Смоленск (4812)29-41-54
 Сочи (862)225-72-31
 Ставрополь (8652)20-65-13
 Сыктывкар (8212)25-95-17
 Сургут (3462)77-98-35
 Тамбов (4752)50-40-97
 Тверь (4822)63-31-35

Казахстан (772)734-952-31

Тольятти (8482)63-91-07
 Томск (3822)98-41-53
 Тула (4872)33-79-87
 Тюмень (3452)66-21-18
 Улан-Удэ (3012)59-97-51
 Ульяновск (8422)24-23-59
 Уфа (347)229-48-12
 Хабаровск (4212)92-98-04
 Чебоксары (8352)28-53-07
 Челябинск (351)202-03-61
 Череповец (8202)49-02-64
 Чита (3022)38-34-83
 Якутск (4112)23-90-97
 Ярославль (4852)69-52-93

<https://exotek.nt-rt.ru> || exox@nt-rt.ru

Термогигрометр TH-610K

Applications

This device measures relative humidity, air temperature (with probe), plus “K” type thermocouple wide temperature measurements. The large, easy-to-read backlit LCD includes primary and secondary displays plus numerous status indicators. Careful use of this meter will provide years of reliable service.

Features

- Semiconductor sensor for temperature measurements of 0°C to 40°C and 32°F~104°F plus type-K thermocouple wide temperature measurements of -20.0°C to 1000°C and -4.0°F~1832°F
- Humidity measurement from 0.1%RH to 100.0%RH with 0.1%RH resolution and fast time response. (The measuring range is from 0% to 100%, but above 98% and below 5% the deviation is not specified.)
- Fast response for Humidity measurement
- Data Hold and MAX Hold function
- Large dual digital LCD display with function indication

Specifications

Function	Range and Resolution	Accuracy
Humidity	5.0 to 98.0% RH	± 3.5% RH
Temperature (K-type) (probe accuracy not included)	-20.0 to 199.9°C	±(3.0% reading + 4°C)
	-20 to 1000°C	
	-4.0 to 199.9°F	±(3.0% reading + 7°F)
	-4 to 1832°F	

Operating Conditions:	32 to 104°F (0 to 40°C); < 80% RH non-condensing
Storage Conditions	14 to 140°F (-10 to 60°C); <80% RH non-condensing
Display:	Dual LCD with Backlight and status Indicators
Sensor Type:	Humidity: Precision capacitance sensor Temperature: Thermistor (probe) and type “K” thermocouple
Sampling Rate:	2.5 samples per second
Dimensions	225 (H) x 45 (W) x 34 (D) mm
Weight:	210 (g)
Battery	One 9V battery, NEDA1604 or 6F22



The Instrument is delivered with:

- 9V battery
- K-type probe
- Soft Case.

