

Алматы (7273)495-231
 Ангарск (3955)60-70-56
 Архангельск (8182)63-90-72
 Астрахань (8512)99-46-04
 Барнаул (3852)73-04-60
 Белгород (4722)40-23-64
 Благовещенск (4162)22-76-07
 Брянск (4832)59-03-52
 Владивосток (423)249-28-31
 Владикавказ (8672)28-90-48
 Владимир (4922) 49-43-18
 Волгоград (844)278-03-48
 Вологда (8172)26-41-59
 Воронеж (473)204-51-73
 Екатеринбург (343)384-55-89

Ижевск (3412)26-03-58
 Иваново (4932)77-34-06
 Иркутск (395)279-98-46
 Казань (843)206-01-48
 Калининград (4012)72-03-81
 Калуга (4842)92-23-67
 Кемерово (3842)65-04-62
 Киров (8332)68-02-04
 Коломна (4966)23-41-49
 Кострома (4942)77-07-48
 Краснодар (861)203-40-90
 Красноярск (391)204-63-61
 Курск (4712)77-13-04
 Курган (3522)50-90-47
 Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
 Москва (495)268-04-70
 Мурманск (8152)59-64-93
 Набережные Челны (8552)20-53-41
 Нижний Новгород (831)429-08-12
 Новокузнецк (3843)20-46-81
 Ноябрьск (3496)41-32-12
 Новосибирск (383)227-86-73
 Омск (3812)21-46-40
 Орел (4862)44-53-42
 Оренбург (3532)37-68-04
 Пенза (8412)22-31-16
 Петрозаводск (8142)55-98-37
 Псков (8112)59-10-37
 Пермь (342)205-81-47

Россия (495)268-04-70

Ростов-на-Дону (863)308-18-15
 Рязань (4912)46-61-64
 Самара (846)206-03-16
 Саранск (8342)22-96-24
 Санкт-Петербург (812)309-46-40
 Саратов (845)249-38-78
 Севастополь (8692)22-31-93
 Симферополь (3652)67-13-56
 Смоленск (4812)29-41-54
 Сочи (862)225-72-31
 Ставрополь (8652)20-65-13
 Сыктывкар (8212)25-95-17
 Сургут (3462)77-98-35
 Тамбов (4752)50-40-97
 Тверь (4822)63-31-35

Казахстан (772)734-952-31

Тольяти (8482)63-91-07
 Томск (3822)98-41-53
 Тула (4872)33-79-87
 Тюмень (3452)66-21-18
 Улан-Удэ (3012)59-97-51
 Ульяновск (8422)24-23-59
 Уфа (347)229-48-12
 Хабаровск (4212)92-98-04
 Чебоксары (8352)28-53-07
 Челябинск (351)202-03-61
 Череповец (8202)49-02-64
 Чита (3022)38-34-83
 Якутск (4112)23-90-97
 Ярославль (4852)69-52-93

<https://exotek.nt-rt.ru> || exox@nt-rt.ru

Инфракрасный термометр IRT-1004P

APPLICATIONS & FEATURES

High Temperature Infrared Thermometers
 IRT-1004P provide fast, easy and accurate readings for most surface temperature measurements.

High 50 to 1, distance to target ratio measures smaller surface areas at greater distances.

Widest temperature range from (-50.0 to 1600 °C -58 to 2912 °F)

Features

- Laser pointer
- Automatic Data Hold
- Statistics: Max, Min, DIFF, AVG, record
- Selectable high and low alarm
- Adjustable emissivity 0.1-1.0
- Over range indication
- User selectable °C or °F
- Laser targeting
- Automatic Data Hold
- Auto power Off
- White Backlit LCD Display

Specifications

Range	-50 °C to 1600 °C/ -58 °F to 2912 °F
Response Time	Less than 1 second
Resolution	0.1 ° up to 1600
Basic Accuracy	-20 to +200 C ± 1.5% of reading or ± 2 °C / ± 4 °F whichever the highest value. For other temperature range see manual.
Size (HxWxD):	230mm×100mm×56mm
Weight:	290g

IRT1004P comes with following accessories:

- 9 Volt battery
- Carrying case
- Gift box
- Mini-tripod for accurate measurements

