

Алматы (7273)495-231
 Ангарск (3955)60-70-56
 Архангельск (8182)63-90-72
 Астрахань (8512)99-46-04
 Барнаул (3852)73-04-60
 Белгород (4722)40-23-64
 Благовещенск (4162)22-76-07
 Брянск (4832)59-03-52
 Владивосток (423)249-28-31
 Владикавказ (8672)28-90-48
 Владимир (4922) 49-43-18
 Волгоград (844)278-03-48
 Вологда (8172)26-41-59
 Воронеж (473)204-51-73
 Екатеринбург (343)384-55-89

Ижевск (3412)26-03-58
 Иваново (4932)77-34-06
 Иркутск (395)279-98-46
 Казань (843)206-01-48
 Калининград (4012)72-03-81
 Калуга (4842)92-23-67
 Кемерово (3842)65-04-62
 Киров (8332)68-02-04
 Коломна (4966)23-41-49
 Кострома (4942)77-07-48
 Краснодар (861)203-40-90
 Красноярск (391)204-63-61
 Курск (4712)77-13-04
 Курган (3522)50-90-47
 Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
 Москва (495)268-04-70
 Мурманск (8152)59-64-93
 Набережные Челны (8552)20-53-41
 Нижний Новгород (831)429-08-12
 Новокузнецк (3843)20-46-81
 Ноябрьск (3496)41-32-12
 Новосибирск (383)227-86-73
 Омск (3812)21-46-40
 Орел (4862)44-53-42
 Оренбург (3532)37-68-04
 Пенза (8412)22-31-16
 Петрозаводск (8142)55-98-37
 Псков (8112)59-10-37
 Пермь (342)205-81-47

Россия (495)268-04-70

Ростов-на-Дону (863)308-18-15
 Рязань (4912)46-61-64
 Самара (846)206-03-16
 Саранск (8342)22-96-24
 Санкт-Петербург (812)309-46-40
 Саратов (845)249-38-78
 Севастополь (8692)22-31-93
 Симферополь (3652)67-13-56
 Смоленск (4812)29-41-54
 Сочи (862)225-72-31
 Ставрополь (8652)20-65-13
 Сыктывкар (8212)25-95-17
 Surgut (3462)77-98-35
 Тамбов (4752)50-40-97
 Тверь (4822)63-31-35

Казахстан (772)734-952-31

Тольятти (8482)63-91-07
 Томск (3822)98-41-53
 Тула (4872)33-79-87
 Тюмень (3452)66-21-18
 Улан-Удэ (3012)59-97-51
 Ульяновск (8422)24-23-59
 Уфа (347)229-48-12
 Хабаровск (4212)92-98-04
 Чебоксары (8352)28-53-07
 Челябинск (351)202-03-61
 Череповец (8202)49-02-64
 Чита (3022)38-34-83
 Якутск (4112)23-90-97
 Ярославль (4852)69-52-93

<https://exotek.nt-rt.ru> || exox@nt-rt.ru

Инфракрасный термометр IRT-1005KDC

Applications

The Psychrometer with InfraRed Thermometer has been designed to combine the functions of a Humidity meter, Type K Thermometer and an Infrared Thermometer. Indispensable for painters to ensure that a surface treatment is made prior to non condensing air.

FEATURES

- Triple digital LCD display
- Slim design with rubberized sides for better grip and for one hand operation
- Low battery indication
- Fast response time when measuring
- Accurate reading
- Auto Power off
- Dual Display & Backlight
- Simultaneous display of: Humidity/Temperature, Humidity/Dew Point, Humidity/Wet Bulb

Function	Range	Resolution	Accuracy
Type K probe Temp.	-100 ~+1372 °C	0.01	± 3 %
InfraRed Temp.	-50 ~ -20°C	0.1 °C	± 5.0
	-20 ~500°C	0.1 /	± 2% reading or ±2°C
Air Temp.	-20 ~ 60°C	0.1°C	±1.0°C
Humidity	10 % ~ 90 %	0.1 % RH	±2%
Wet Bulb	0 ~ 80°C	0.1°C	± 0.5 °C
Dew Point	-30 - 100°C	0.1°C	± 0.5 °C

Dimensions	257 x 76 x 53(mm)
Display size:	43 x 57 (mm)
Weight:	355 (g)

The Instrumnet is delivered with:

- 9V battery
- type K temperature probe,
- gift box and carrying case.

