

Алматы (7273)495-231

Ангарск (3955)60-70-56

Архангельск (8182)63-90-72

Астрахань (8512)99-46-04

Барнаул (3852)73-04-60

Белгород (4722)40-23-64

Благовещенск (4162)22-76-07

Брянск (4832)59-03-52

Владивосток (423)249-28-31

Владикавказ (8672)28-90-48

Владимир (4922) 49-43-18

Волгоград (844)278-03-48

Вологда (8172)26-41-59

Воронеж (473)204-51-73

Екатеринбург (343)384-55-89

Ижевск (3412)26-03-58

Иваново (4932)77-34-06

Иркутск (395)279-98-46

Казань (843)206-01-48

Калининград (4012)72-03-81

Калуга (4842)92-23-67

Кемерово (3842)65-04-62

Киров (8332)68-02-04

Коломна (4966)23-41-49

Кострома (4942)77-07-48

Краснодар (861)203-40-90

Красноярск (391)204-63-61

Курск (4712)77-13-04

Курган (3522)50-90-47

Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13

Москва (495)268-04-70

Мурманск (8152)59-64-93

Набережные Челны (8552)20-53-41

Нижний Новгород (831)429-08-12

Новокузнецк (3843)20-46-81

Ноябрьск (3496)41-32-12

Новосибирск (383)227-86-73

Омск (3812)21-46-40

Орел (4862)44-53-42

Оренбург (3532)37-68-04

Пенза (8412)22-31-16

Петрозаводск (8142)55-98-37

Псков (8112)59-10-37

Пермь (342)205-81-47

Ростов-на-Дону (863)308-18-15

Рязань (4912)46-61-64

Самара (846)206-03-16

Саранск (8342)22-96-24

Санкт-Петербург (812)309-46-40

Саратов (845)249-38-78

Севастополь (8692)22-31-93

Симферополь (3652)67-13-56

Смоленск (4812)29-41-54

Сочи (862)225-72-31

Ставрополь (8652)20-65-13

Сыктывкар (8212)25-95-17

Сургут (3462)77-98-35

Тамбов (4752)50-40-97

Тверь (4822)63-31-35

Тольятти (8482)63-91-07

Томск (3822)98-41-53

Тула (4872)33-79-87

Тюмень (3452)66-21-18

Улан-Удэ (3012)59-97-51

Ульяновск (8422)24-23-59

Уфа (347)229-48-12

Хабаровск (4212)92-98-04

Чебоксары (8352)28-53-07

Челябинск (351)202-03-61

Череповец (8202)49-02-64

Чита (3022)38-34-83

Якутск (4112)23-90-97

Ярославль (4852)69-52-93

Киргизия (996)312-96-26-47

Россия (495)268-04-70

Казахстан (772)734-952-31

<https://exotek.nt-rt.ru> || exox@nt-rt.ru

Инфракрасный термометр IRT-1006

APPLICATIONS & FEATURES

Infrared Thermometers IRT-1006 provide fast, easy and accurate readings for most surface temperature measurements.

Features:

- Laser pointer
- Over range indication
- User selectable measuring Unit °C or °F
- Auto power Off
- Backlit LCD Display

Specifications

DISPLAY	3-1/2 digit (1999count) LCD with backlighting
MEAS. RANGES	-50.0 °C to 550°C/-58.0 °F to 1022 °F
ACCURACY	-50 °C - -20 °C = ± 5 °C -20 °C -+550 °C = ± 2% or ± 2 °C
RESOLUTION	-50 °C -+200 °C = 0,1 °C +201 °C -+550 °C = 1 °C
SAMPLE RATE	2.5 times/second.
OVER RANGE INDICATION	LCD will show “1”
EMISSIVITY	0.95 fixed value
FIELD OF VIEW	D/S = Approx. 8:1 ratio (D = distance, S = spot)(Has 90% encircled energy at the focal point)
DIODE LASER	Output <1mW, Wavelength 630~670nm,class 2 (II) Laser product
SPECTRAL RESPONSE	6~14um
POWER OFF	Automatic shut off after 7 seconds, approx.
OPERATING TEMP.	0 °C to 50°C (32 °F to 122 °F)
STORAGE TEMP.	-20 °C to 60°C (-4 °F to 140°F)
RELATIVE HUMIDITY	10 %~90 %RH operating, <80%RH storage
POWER SUPPLY	9V battery, NEDA 1604A or IEC 6LR61, or equivalent
WEIGHT	180g.
SIZE	82 x 41.5 x 160mm

IRT1006 comes with following accessories:

- 9 Volt battery
- Holster

